

DEUTSCH

Installation - schnell und einfach:

1. ZIP File Downloaden. Auf Ihrer Festplatte speichern
2. Legen Sie sich auf Ihrer Festplatte ein beliebiges Verzeichnis an, z.B. PCWaageWin
3. Öffnen Sie die ZIP File im Explorer.
4. Kopieren Sie alle Dateien aus dem ZIP in das neue Verzeichnis
5. Starten Sie den PCWaageWIN EXE File!
6. Verbinden Sie Waage und PC
7. Öffnen Sie --> Setup --> COM Port Settings. Stellen Sie den COM Port auf die Übertragungsparameter Ihrer Waage ein
8. Wählen Sie in der Hauptmaske einen COM Port
9. Öffnen Sie den COM Port
10. Wiegedaten werden in der Anzeige dargestellt. Betätigen Sie den Button SPEICHERN, um Wiegedaten in der Datei DATA.XML zu speichern.

ENGLISH

Take your installation in few steps:

1. Download ZIP file. Save ZIP file to your local hard disc
2. Create a folder at your hard disc, e.g. PCWaageWin
3. Open ZIP file with your Explorer
4. Copy all files from ZIP into your new folder
5. Start PCWaageWIN EXE file
6. Make serial connection between weight system and your local PC
7. Use --> Setup --> COM Port Settings. Configure your COM port to serial parameters of your weight system
8. Select a COM port in the main window
9. Open the COM port
10. The program shows weight information in the main window. Use the button SAVE to save data into file DATA.XML

Lokaler Datenträger (J:)

- bilder
- demo
- demolager
- downloads
- mails
- PCWaageWin
- Recycled
- vb
- Websites

Ordner

- 1.0.2-inwork
- DATA.xml
- PC-Waage-WIN-DE.exe
- PC-Waage-WIN-EN.exe
- Readme-PCWaageWin-DE.pdf
- waage-demo.jpg

PC Waage WIN

File User Setup

DE 1.0.2 **DemoVersion - nur für Test und Demo!**

Customer / Order No:

Art No:

COM Port
COM1
COM2

Akt. Wiegung

0,00 kg

☐ AutomaticMode

TimeStamp	User	Kunde	Artikel	Gewicht
-----------	------	-------	---------	---------

PC Waage WIN. (c)AE SYSTEME www.terminal-systems.de D-31303 Burgdorf